ABSTRACT

A method for granulating a flexible polyolefin resin including steps of melting a flexible polyolefin resin, and melt-kneading the resin while cooling the resin to a temperature of the melting point (Tm-D) of the resin or less.